


March 14, 2016

## Pictures



### *What happened and where?*

On January 25, 2016 a significant rock slide occurred at Gallagher Lake which impacted a siphon on the canal irrigation system which provides irrigation water to the Town of Oliver, Electoral Area C (rural Oliver), and Osoyoos Indian Band. The break is near station 2+055 on the flume section at Gallagher Lake.

### *Current events*

On Monday, March 7, 2016 Town of Oliver staff and engineers were able to enter the siphon through a coordinated effort with the rock scalers.

You can see from the pictures the damage is significant to the siphon; the roof has collapsed in one section as much as 2 feet or .61 meters.

Based on the visual analysis the best temporary option for repair is to insert 2 sleeves inside the siphon. This is a temporary solution for the irrigation season and cannot guarantee a 100% fix if there are more damages or settlement.

Rock scaling will shut down on March 18<sup>th</sup> to allow the engineers and Town staff to reassess and determine when and if scaling work continues.

The Town is also looking to a more permanent fix which will involve additional rock scaling in the irrigation off-season.

Communication with Provincial Ministries and agencies is ongoing.

Mayor and Council are lobbying the Province of British Columbia for funding assistance for this natural disaster.

## *Works Schedule*

March 11 – 18	Additional scaling and work site safety
March 11 – 18	Coordinate materials and contractors
March 19 – 25	Contractor start works inside siphon (longer if necessary)
April 1	Open Canal (upper section only)
April 4 – 5	Inspect works
April 11	Fill system for irrigation turn on

## *Communication*

All communications and updates will be through the Town of Oliver website [www.oliver.ca](http://www.oliver.ca), click on **Gallagher Lake Rock Slide – Quick Link** on the Home Page.

## *Background*

This section of siphon was installed in 1997 to help minimize and eliminate damages to the existing canal system. It is a 1950 mm (78”) diameter reinforced concrete pipe buried over with approximately 3 m of fill. It was engineered to withstand a great force if more debris were to fall. The fill was unable to withstand the force and direct damage occurred.